



4F SERVICES SAGL

+41 (0) 91 225 54 90 Via Cügn n°2 Novazzano CH info@4fservices.ch CHE-215.990.951

CAR WASH OPERATING MANUAL

Lüster car wash range — dilution, application and safety instructions for staff

Print and hand to every employee. Dilutions must be followed exactly: correct dosing guarantees the result and keeps the cost per wash under control. If in doubt, contact the manager or 4F Services before proceeding.

NeroGomma — Protective tyre shine, wet-look finish (art. 60001)

Dilutions and dosing

Undiluted / spot stains	Puro	5 ml / ruota	±2'000 ruote
Manual use / sprayer	1:1	500 ml / 1 L	20 L

Step-by-step procedure

1. Shake the product well before use.
2. Apply neat with a sponge or applicator onto the clean, dry surface.
3. Spread evenly with circular movements.
4. Leave to air-dry: do not rinse or buff.

Contact time: No rinsing · **Available sizes:** 10 kg, 25 kg · **Mandatory PPE:** Nitrile gloves, Safety goggles

WARNING: Apply to tyre sidewalls only, never on tread or pedals: slippery surface. Do not use on motorbikes or bicycles.

Le istruzioni e informazioni riportate su questo documento sono frutto di esperienze di laboratorio e pratico impiego e quindi accurate e pertinenti. Essendo le reali condizioni di utilizzo da parte degli utenti al di là di ogni nostra possibilità di controllo, esse vengono fornite da parte nostra senza alcuna responsabilità o garanzia implicita o esplicita. Per ulteriori informazioni Vi preghiamo di contattare il nostro Servizio Tecnico.



4F SERVICES SAGL

+41 (0) 91 225 54 90 Via Cügn n°2 Novazzano CH info@4fservices.ch CHE-215.990.951

GeloStop — Concentrated radiator antifreeze, protection down to -40 °C (art. 60002)

Dilutions and dosing

Mild climate	33 %	1 parte / 2 parti acqua	-18 °C
Normal winter	50 %	1 parte / 1 parte acqua	-37 °C
Harsh winter	60 %	3 parti / 2 parti acqua	-50 °C

Step-by-step procedure

1. Prepare the mixture at the chosen concentration following the table.
2. Pour into the vehicle's dedicated tank or reservoir.
3. Check the level and complete the fill.
4. Record the concentration used in the wash station log.

Contact time: Do not rinse · **Available sizes:** 25 kg, Fusto 200 kg · **Mandatory PPE:** Nitrile gloves, Safety goggles

WARNING: With a cold engine. Do not mix with antifreeze of a different technology (IAT/HOAT): if in doubt, drain and refill the circuit. Dispose of as special waste.

VetroGelo — Concentrated antifreeze screenwash for car and truck reservoirs, down to -30 °C (art. 60003)

Dilutions and dosing

Mild climate	1:2	330 ml / 1 L	-10 °C
Normal winter	1:1	500 ml / 1 L	-20 °C
Harsh winter	Puro	1 L / 1 L	-30 °C

Step-by-step procedure

1. Prepare the mixture at the chosen concentration following the table.
2. Pour into the vehicle's dedicated tank or reservoir.
3. Check the level and complete the fill.
4. Record the concentration used in the wash station log.

Contact time: Do not rinse · **Available sizes:** 25 kg, Fusto 200 kg · **Mandatory PPE:** Nitrile gloves

WARNING: Fill the washer reservoir only, never the cooling circuit. If the reservoir is already frozen, thaw it first in a warm room.

Le istruzioni e informazioni riportate su questo documento sono frutto di esperienze di laboratorio e pratico impiego e quindi accurate e pertinenti. Essendo le reali condizioni di utilizzo da parte degli utenti al di là di ogni nostra possibilità di controllo, esse vengono fornite da parte nostra senza alcuna responsabilità o garanzia implicita o esplicita. Per ulteriori informazioni Vi preghiamo di contattare il nostro Servizio Tecnico.



4F SERVICES SAGL

+41 (0) 91 225 54 90 Via Cügn n°2 Novazzano CH info@4fservices.ch CHE-215.990.951

FrenoNet — Fast-evaporating brake and mechanical parts cleaner (art. 60005)

Dilutions and dosing

Undiluted / spot stains	Puro	Spruzzo diretto	—

Step-by-step procedure

1. Access the brake assembly following the workshop procedure (wheel removed).
2. Spray the product neat onto the parts to be cleaned from 10–20 cm away.
3. Let the dissolved dirt drip off and the product evaporate completely.
4. Reassemble and check correct operation before driving.

Contact time: Evaporates in 1–2 min · **Available sizes:** 5 kg, 25 kg · **Mandatory PPE:** Nitrile gloves, Safety goggles, Respirator mask

WARNING: Use in a ventilated area, away from flames and hot surfaces. Do not spray for prolonged periods on painted plastic or rubber.

SchiumaLux — Concentrated active foam for gantries and self-service bays (art. 60006)

Dilutions and dosing

Gantry / automatic dosing	0,5–1 %	5–10 ml / 1 L	2'500–5'000 L
Self-service bay / foam lance	1:4	200 ml / 1 L	125 L
Manual use / sprayer	1:10	100 ml / 1 L	250 L

Step-by-step procedure

1. Dilute the concentrate in the foam lance or tank according to the table.
2. Spread the foam over the vehicle from bottom to top.
3. Leave to act for 3–5 minutes without ever letting the foam dry.
4. Rinse with the pressure washer from top to bottom.

Contact time: 3–5 min · **Available sizes:** 25 kg, Fusto 200 kg · **Mandatory PPE:** Nitrile gloves, Safety goggles

WARNING: Do not let the foam dry on the bodywork, especially in the sun. Adjust the dosing unit on the first vehicle and record the setting.

Le istruzioni e informazioni riportate su questo documento sono frutto di esperienze di laboratorio e pratico impiego e quindi accurate e pertinenti. Essendo le reali condizioni di utilizzo da parte degli utenti al di là di ogni nostra possibilità di controllo, esse vengono fornite da parte nostra senza alcuna responsabilità o garanzia implicita o esplicita. Per ulteriori informazioni Vi preghiamo di contattare il nostro Servizio Tecnico.



4F SERVICES SAGL

+41 (0) 91 225 54 90 Via Cügn n°2 Novazzano CH info@4fservices.ch CHE-215.990.951

CeraLux — Hydrophobic protective wax, fast drying, for gantries (art. 60007)

Dilutions and dosing

Gantry / automatic dosing	0,2–0,5 %	2–5 ml / 1 L	5'000–12'500 L
Self-service bay / foam lance	1:100	10 ml / 1 L	2'500 L

Step-by-step procedure

1. Pour the concentrate into the system's suction drum or connect the automatic dosing unit.
2. Set the concentration on the dosing unit according to the dilution table.
3. Run a full cycle and check the result on the first vehicle.
4. Check product level, filters and nozzles weekly.

Contact time: 30–60 sec · **Available sizes:** 10 kg, 25 kg · **Mandatory PPE:** Nitrile gloves

WARNING: Dose at the minimum and increase only if drying is incomplete: too much product leaves haze on the glass. Do not exceed the maximum concentration.

CerchiNet — Wheel cleaner with iron decontamination and purple indicator (art. 60008)

Dilutions and dosing

Undiluted / spot stains	Puro	Spruzzo diretto	±40 cerchi/L
Manual use / sprayer	1:1	500 ml / 1 L	20 L

Step-by-step procedure

1. Apply the product neat or diluted onto the cold, dry surface.
2. Leave to act for the indicated contact time, without letting it dry.
3. Work stubborn dirt with a brush or sponge.
4. Rinse thoroughly with water, ideally under high pressure.

Contact time: 2–3 min · **Available sizes:** 10 kg, 25 kg · **Mandatory PPE:** Nitrile gloves, Safety goggles

WARNING: Apply on cold wheels in the shade. Do not let it dry: once the purple change is complete, rinse immediately under high pressure.

Le istruzioni e informazioni riportate su questo documento sono frutto di esperienze di laboratorio e pratico impiego e quindi accurate e pertinenti. Essendo le reali condizioni di utilizzo da parte degli utenti al di là di ogni nostra possibilità di controllo, esse vengono fornite da parte nostra senza alcuna responsabilità o garanzia implicita o esplicita. Per ulteriori informazioni Vi preghiamo di contattare il nostro Servizio Tecnico.



4F SERVICES SAGL

+41 (0) 91 225 54 90 Via Cügn n°2 Novazzano CH info@4fservices.ch CHE-215.990.951

B-Lux — Antistatic ready-to-use glass and surface cleaner (art. 20005)

Dilutions and dosing

Routine maintenance	Pronto uso	Spray da 30 cm	750 ml
Heavy soil	Pronto uso	Spray + qualche secondo di posa	750 ml

Step-by-step procedure

1. Dilute in the spray bottle following the graduated scale.
2. Spray evenly over the surface to be treated.
3. Leave to act for the indicated contact time.
4. Wipe off with a clean microfibre cloth.

Contact time: A few seconds · **Available sizes:** 750 ml

Il Marsigliese — Universal super-active degreaser (art. 30007)

Dilutions and dosing

Routine maintenance	1:10	100 ml / 1 L	10 L
Heavy soil	1:5	200 ml / 1 L	5 L
Undiluted / spot stains	Puro	su macchie ostinate	—

Step-by-step procedure

1. Dilute in the spray bottle following the graduated scale.
2. Spray evenly over the surface to be treated.
3. Leave to act for the indicated contact time.
4. Wipe off with a clean microfibre cloth.

Contact time: 2–5 min · **Available sizes:** 750 ml

Le istruzioni e informazioni riportate su questo documento sono frutto di esperienze di laboratorio e pratico impiego e quindi accurate e pertinenti. Essendo le reali condizioni di utilizzo da parte degli utenti al di là di ogni nostra possibilità di controllo, esse vengono fornite da parte nostra senza alcuna responsabilità o garanzia implicita o esplicita. Per ulteriori informazioni Vi preghiamo di contattare il nostro Servizio Tecnico.



4F SERVICES SAGL

+41 (0) 91 225 54 90 Via Cügn n°2 Novazzano CH info@4fservices.ch CHE-215.990.951

Rocket — Alkaline industrial floor detergent (art. 50001)

Dilutions and dosing

Routine maintenance	1:100	10 ml / 1 L	100 L
Heavy soil	1:50	20 ml / 1 L	50 L
Industrial / deep cleaning	1:20	50 ml / 1 L	20 L

Step-by-step procedure

1. Dilute the concentrate according to the table, respecting local water hardness.
2. Apply to the surface with a cloth, sponge or professional tool.
3. Leave to act for the indicated contact time.
4. Wipe off with a clean cloth or rinse with water.

Contact time: 5 min in scrubber-dryer · **Available sizes:** 20 kg

No Calc F — Strong acidic descaler for machines and surfaces (art. 10006)

Dilutions and dosing

Routine maintenance	1:10	100 ml / 1 L	10 L
Heavy soil	1:5	200 ml / 1 L	5 L

Step-by-step procedure

1. Dilute the concentrate according to the table, respecting local water hardness.
2. Apply to the surface with a cloth, sponge or professional tool.
3. Leave to act for the indicated contact time.
4. Wipe off with a clean cloth or rinse with water.

Contact time: 5–15 min · **Available sizes:** 10 kg

Document generated on 09.10.2026 — 4F Services Sagl, Novazzano. Full safety data sheets (SDS): luster-shop.ch/sicurezza-prodotti. Reprint when the product range is updated.

Le istruzioni e informazioni riportate su questo documento sono frutto di esperienze di laboratorio e pratico impiego e quindi accurate e pertinenti. Essendo le reali condizioni di utilizzo da parte degli utenti al di là di ogni nostra possibilità di controllo, esse vengono fornite da parte nostra senza alcuna responsabilità o garanzia implicita o esplicita. Per ulteriori informazioni Vi preghiamo di contattare il nostro Servizio Tecnico.